

**B.Tech. SEM -IV Mechanical 2014 Course (CBCS) : WINTER -
2017**

SUBJECT : MATERIAL SCIENCE

Day : **Wednesday**
Date : **22/11/2017**

Time : **02.30 PM TO 05.30 PM**
Max. Marks : 60

W-2017-2095

N.B.:

- 1) All questions are **COMPULSORY**.
- 2) Figures to the right indicate **FULL** marks.
- 3) Use of non-programmable **CALCULATOR** is allowed.
- 4) Assume suitable data if necessary.

-
- Q.1** a) Define the following terms: [05]
- | | |
|---------------------------|------------------------------|
| i) Dislocation | iii) Recrystallization |
| ii) Atomic packing factor | iv) Single crystal structure |
| v) Slip | |
- b) Explain the role of imperfections in plastic deformation of polycrystalline materials. [05]

OR

- a) Find the number of atoms/cm² on (001) and (101) planes of Copper (F.C.C.) if $r = 2.07 \text{ \AA}$. [05]
- b) What is work hardening? How does it occur? Also explain why strain hardening does not occur in hot working. [05]

- Q.2** a) Find out the hardness number from following data: [05]
- i) If the steel block is tested under the 2.5 mm ball indenter and 100 kg load gives circular impression of diameter 1.4 mm.
 - ii) Copper plate is tested by diamond indenter with load 120 kg and observe square impression of diagonal length $d_1 = 0.791$ and $d_2 = 0.898$ mm.
- b) Explain the factors to be considered while selecting the NDT technique for the particular applications. [05]

OR

- a) Suggest suitable NDT methods that might be used to identify: [05]
- i) Surface defects with a copper metal.
 - ii) Internal flaws in steel block.
 - iii) Shrinkage cavity in Aluminium casting.
 - iv) Residual stresses in steel wire.
- b) How is the creep life and fatigue life of the component improved? [05]

- Q.3** a) Explain the methods of plotting an equilibrium diagram by use of cooling curves. [05]
- b) What is a dendrite? Explain the mechanism of formation of dendrites. [05]

OR

P.T.O.

- a) Explain the following in brief: [05]
i) Gibbs Phase rule
ii) Uses of Eutectic alloys

- b) Construct a phase diagram for the system A – B from the following data: [05]
M.P. of A = 1000°C, M.P. of B = 800°C
Eutectic point = 500°C at 40% B.
Maximum solubility of A in B at 500°C = 10%.
Maximum solubility of B in A at 500°C = 20%.
And solubility decreases with temperature to 5% in each other.
Label the phase diagram.
Calculate the phases at 35% B and show the cooling of this alloy from high temperature to room temperature.

- Q.4 a) Define the following structural components: [05]
i) Ferrite iii) Cementite
ii) Austenite iv) Pearlite
v) Ledeburite

- b) List out the different types of cast iron and its properties, phases and applications. [05]

OR

- a) Describe the three reactions that occur in the Iron – Iron carbide system. [05]
b) Explain Nodular cast iron and state its manufacturing method [05]

- Q.5 a) What is precipitation hardening? Explain with a suitable example of such alloys. [05]
b) Draw the copper – zinc equilibrium diagram and give the types of brasses. [05]

OR

- a) What is the LM series? What do you mean by LM6 and LM11? [05]
b) Explain the significance of zinc in brasses. [05]

- Q.6 a) Explain the details about PVD processes and Ion implantation. [05]
b) What is passivity? Explain in detail the theories of passivity. [05]

OR

- a) Explain the role of design considerations and changes in environmental conditions in corrosion prevention methods. [05]
b) Explain in detail about stress corrosion cracking and intergranular corrosion. [05]

* * * *